SEP 1 2 1995

_____, Recorded Plat ___

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF CHARLEYOIX RECEIVED FOR RECORD

95 AUG -4 AM 9: 17

Property in Sec.

Located In: Corner Code ## Public Land Survey T __32NR __5W <u>C-1</u> T _____ R ____ **Property Controlling** S ____ T ___ R __ in Section Miscellaneous S ____ T ___ R ___

Charles 13 Balle REGISTER OF DEEDS

Register of Deeds Stamp & File Number

.	Private	Clai	ims	 	 · ,	 —
					O the corner noi	

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO Set Post Cor Secs 31 & 32 (T33N-R5W which is also cor. to Sec 5 & 6 T32N-R5W)

1. Sugar 16N 35E 68

2. Sugar 14N 83W 32 John Mullett, May 1840 Ironwood comer post E.A. Robinson, May 1906 Set 1"x40" Iron Stake, Dec 1913, no mention of witnesses.

10 11 12

Fd 1"x40" Robinson pipe and set DNR Mon and Cedar Post in 1974 Carl Roser LCRC L. 2 Pg 6

- 3. 8" Maple S23°E 6.66
- 4. 10" Maple N11°E 21.65
- 5. 9" maple N84°W 13.40
- 6. In fence cor fence N-S-E-W Used in subsequesnt surveys same unit
- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner: DNR Mon Fd
 - 3. Fd Spk 10" Maple S23°E 6.78'
 - 4. Fd Spk 12" Maple N11°E 21.72"
 - 5. Fd Spk and Tag 10" Maple S23°E 6.78
 - Fd Spk 20" Poplar N45°W 10.35'

GLO to B-1 2640 Robinson 1913, 2630.4 Roser 1975 2634.3 GLO to D-1 2640 Roser 2623.63 1982

Charleveix Co. Surveyor Signature Mary C Frendt Date: July 20, 1998 PA 345 of 1990

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1 DNR Mon

- 3. Fd Spk 10" Maple S23°E 6.78'
- Fd Spk 12" Maple N11°E 21.72'
 Fd Spk and Tag 10" Maple S23°E 6.78
- 6. Fd Spk 20" Poplar N45°W 10.35"

And is accepted as a careful and faithful pertetuation of the position of the original corner.

WAYNE E.
BOSS
PROFESSIONAL
SURVEYOR
NO.
20703

∎ned by .

Date July 28, 1995

veyor's Michigan License No. _

002 FAGE 385 20703 Liber

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983