

SURVEY &
RE-MONUMENTATION

SEP 12 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

95 AUG -4 AM 9:22

For corners in

COMMISSION

Charles M. Baker
REGISTER OF DEEDS

Charlevoix
(County)

Located In:

Corner Code #

- | | | | | | |
|-------------------------|---|-----|---|----|-----|
| 1. Public Land Survey | T | 32N | R | 5W | H-1 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling | S | | T | R | |
| in Section | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Sec. | S | | T | R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Wayne E. Boss, in a field survey on May 24, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO Set 1/4 Sec post
1. Beech 10, N62W, 31
2. Cedar 10, N69E, 12
John Mullett, 1840

E.A. Robinson in Sep 1923
Used cor he states was set by Skeels, no record of Skeels survey Fd, no witnesses given.

Roser Fd 1 1/4" pipe that he states fits EAR Survey in 1923. Roser replaced pipe w/ DNR Mon & Cedar Post in 1982.
3. 10" Balsam S05°E, 15.5
4. 9" B. Cherry W40°E, 31.2
5. CTR N-S winding gravel road, East 200' ±.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd DNR Mon

3. Fd. 10" Balsam S05°E, 15.5
4. Fd. 9" B. Cherry W40°E, 31.2
5. Fd. CTR N-S winding gravel road, East 200' ±.

GLO to H-1 to G-1 2640
GLO to H-1 to I-1 2640

Roser 1982 - 2617.68
Roser 1982 - 2615.53

Charlevoix Co. Surveyor
APPROVED

Signature Mary C. Feinelt
Date July 20, 1995
P.A. 345 of 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-1 Fd. DNR Mon & Cedar Post

3. Fd. 10" Balsam S05°E, 15.5
4. Fd. 9" B. Cherry W40°E, 31.2
5. Fd. CTR N-S winding gravel road, East 200' ±.
8. Set Spk 12" W Birch S35°E, 21.10

And is accepted as a careful and faithful re-establishment of the position of the original corner.



igned by *Wayne E. Boss* Date July 28, 1995
urveyor's Michigan License No. 20703 002 390