

SEP 12 1995

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

95 AUG -4 AM 9:23

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMISSION

Charlene M. Perkins
REGISTER OF DEEDS

Charlevoix (County)	Located In:	Corner Code #
1. Public Land Survey	T 32N R 5W	I-1
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Wayne E. Boss, in a field survey on May 24, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO set post cor sec 34 & 35 (T33N-R5W also cor to Sec's 2 & 3 T32N-R5W)

1. Beech 20 N20E, 39
2. Sugar 10 N40W, 46
3. Sugar 16 S59E, 51
4. Beech 12 S23W, 27

E.A. Robinson Feb 1906 states a beech post set and to be replaced w/RR Iron 3/6" long (No witnesses given)

Re-established cor at old cor fence post. Remains fr's N-S-E-W cor fits previous surveys & occupancy (Rds & fns)
Roser 1982 in LCRC L. 2 Pg 145
DNR Mon set and cedar post
5. 9" Maple N55°E, 19.0
6. 8" Twin Maple N10°W, 10.1
7. 13" Maple S15°W, 23.6

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Charlevoix Co. Mon set from Roser Witnesses

6. Fd 8" Twin Maple N10°W, 10.1
7. Fd 13" Maple S15°W, 23.6

GLO I-1 to H-1 2640
GLO I-1 to J-1 2640

Roser 1982 2615.53
EAR 2618.9 Roser 2628.54

Charlevoix Co. Surveyor
APPROVED
Signature Mary C. Feinelt
Date: July 20, 1995
PA 345 of 199

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-1 Charlevoix Co. Mon Set

6. Set Spk 8" Twin Maple N10°W, 10.83'
7. Set Spk 13" Maple S15°W, 24.08'
8. Set Spk 18" Maple S87°E, 17.73'
9. Set Spk 6" Twin Maple N70°W, 15.83'

And is accepted as a careful and faithful re-establishment of the position of the original corner.



Signed by Wayne E. Boss Date July 28, 1995
Surveyor's Michigan License No. 20703

Lot # 002 Sub 391