SURVEY & REMONUMENTATION

JAN 2 6 1998

, Recorded Plat

STATE OF MICHIGAN COUNTY OF CHAPLEVOIX RECEIVED FOR RECORD

or corners in	SECTION	LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970		97 DEC 15 PM 2: 47
Charlevoix (County)	Located In:	Corner Code #	,	REGISTER OF DEEDS

co. Co.de. STER OF DEEDS

(County)		
1. Public Land Survey	T_32NR_7W T_R_ T_32NR_8W	A-9 M-9
Property Controlling in Section Miscellaneous Property in Sec.	TR STR STR STR STR	

Register of Deeds Stamp & File Number

5. Private Claims Wayne E. Boss May 97 In a field survey on 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Roard of Land Surveyors or by a Decree of a Court of Law anticipated to exterit labed to exteri Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- 3 5 6 7 11
- A. Description of original monument and accessories and/or subsequent restoration:
 - **A-9 OCTOBER 1856** E.D., ATWATER, DEPUTY SURVEYOR LAWRENCE R. FEINDT **SET SUGAR POST 3 INCH**

MAY 23, 1978 FOUND 1" PIPE

1. SUGAR 8 INCH N8 1/2W 24 LKS.

3. 10" MAPLE N80E 35.4'

2. BEECH 6 INCH S18 3/4W 17 LKS.

4. 10" MAPLE \$45W 40.12"

- 5. 4" MAPLE N50W 17.85"
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

MIE 130

A-9 **MAY 1997** FOUND 1" GALVANIZED PIPE 3. 14" MAPLE N80E 35.97' NO OTHER WITNESSES NOTED

Charlevoix Co. Surveyor APPROVED. Signaturo Mary C. Ferndt
Dato: 10 163-97

. Description	on of monument for corner and accessories established to p	erpetuate locating the position of the corner OF MICH.
4.0		HAME STATEMENT OF THE PARTY OF
A-9	1" GALVANIZED PIPE REPLACED WITH CHARLE	VOIX COUNTY CONCRETE MONUMENTINE E. ***
	3. 14" MAPLE N80E 35.97' SET SPIKE & TAG 6. 1" GALVANIZED PIPE AS GUARD	t BOSS
	7. TWIN 12" MAPLE S50W 4.12' SET NAIL & TAG	PROFESSIONAL CE
	8. 6" MAPLE N80W 18.51' SET NAIL & TAG	20703 - 20703
	9. 8" IRONWOOD N40E 26.88' SET NAIL & TAG	
	AND IS ACCEPTED AS A CAREFUL & FAITHFUL	REESTABLISHMENT OF THE POSITION OPPOSITE AND COLLAR
	CORNER	/ / / ON THE TOUR SHOULD IN ALL
V	Ma hatist	1.7/1.
Signed by		Date/ 2 / / 2 / 9 7
surveyor's M	ichigan License No. 70703	
	(Inch o o o 1	
	rintkuu3 Mae 130	FORM ADDROVED BY MICHICAN STATE COADS OF TOTAL