

SURVEY & REMONUMENTATION

OCT 19 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED

98 SEP -8 PM 2:06

Charles E. Feindt
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in
Charlevoix

Located In:

Corner Code #

(County)

1. Public Land Survey

T 32N R 7W D-13
T R
T 31N R 7W D-1 ANTRIM
T R

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

4. Lot No. , Recorded Plat

5. Private Claims

Wayne E. Boss

June

98

I, , in a field survey on , 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

D-13 OCTOBER 23, 1856

EDWARD D. ATWATER, DEPUTY SURVEYOR
SET POST, 0.3 CHAINS EAST OF STREAM
NO OLD CORNER FOUND

1) YELLOW BIRCH 7 INCH N12*W 23 LINKS
2) HEMLOCK 9 INCH S17*E 21 LINKS

MAY 7, 1984 NICHOLAS B. DEYOUNG, P.S.
FD. 1 1/2" PIPE, 5) 6" POPLAR N5*E 35.1',

3) 5" POPLAR S30*E 32.1', 6) 10" MAPLE N80*W 92.8', 7) S. END OF CULVERT S40*W 32.4'

OCTOBER 11, 1973 MARY C. FEINDT, P.S. FOUND IRON

JULY 31, 1979 ARTHUR LENNOX, P.S. FD. IRON IN 11/2" PIPE
3) 6" MAPLE S30*E 32.07', 4) 12" POPLAR N70*W 25.50'
5) 5" POPLAR N10*E 35.35'

MARCH 16, 1994 JAMES E. EVANS, P.S. FD. 11/2" PIPE
(3) 6" MAPLE S30*E 32.02' FD. SPIKE 9) 8" POPLAR N59W 92.90'
10) 5" POPLAR N73W 71.75', 11) 3" PINE N20*W 33.84' FD. SPIKE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-13

FEB. 20, 1998 FOUND CONCRETE MONUMENT 8" BELOW ROAD SURFACE

9) 6" POPLAR N61*W 93.2' FOUND NAIL SOUTHEAST FACE

11) 2" CEDAR N20*W 34.1' FOUND NAIL S. FACE

10) 3" POPLAR N74*E 72.1' FOUND NAIL SW FACE

(3) 5" BASSWOOD S34*E 32.3' FOUND NAIL NW FACE
SMALL CREEK WEST 13'

E-13 TO D-13 GLO 40 CHAINS (2640') MEASURES 2627.77'

D-13 TO MC EAST OF LAKE GLO 37.50 CHAINS (2475.0' MEASURES 2473.16'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-13

CONCRETE MONUMENT AS FOUND

9) 6" POPLAR N61*W 93.2' NAIL AS FOUND

11) 2" CEDAR N20*W 34.1' NAIL AS FOUND

10) 3" POPLAR N74*E 72.1' NAIL AS FOUND

(3) 5" BASSWOOD S34*E 32.3' NAIL AS FOUND

AND IS ACCEPTED AS CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER

Signed by *Wayne E. Boss*

Date *Aug 24, 1998*

Surveyor's Michigan License No. *20703*

Charlevoix Co. Surveyor
APPROVED

Signature *Mary C. Feindt*
Date: *Aug 13, 1998*

