

SURVEY & REMONUMENTATION

FEB 22 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECORDED FOR FILING

96 DEC 11 PM 3:10

Charles M. Feindt
REGISTER OF DEEDS

For corners in
Charlevoix

(County)

Located In:

Corner Code #

1. Public Land Survey

T 32N R 7W

L-1 ✓

T 33N R 7W

L-13

T R

T R

2. Property Controlling

S T R

In Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Wayne E. Boss, in a field survey on OCTOBER 14, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-1 GLO JUNE 1839 JUNE 1886 MAY 1978
JOHN HODGSON E.K. ROBINSON LAWRENCE FEINDT
SET ¼ SEC. POST FD. ¼ POST SET CHARL. CO. MON MIDWAY BETWEEN SEC. CORNERS
1. BIRCH 8 N28E 20 NO NEW WIT. LCRC L.2 P.71
2. BIRCH 16 N74W 34 (CORRECTED OCT. 1983 & AGAIN IN FEB 1986)
3. N75E 20.70' 5" MAPLE
4. S40E 9.09' 5" MAPLE
5. N45W 17.28' 12" MAPLE 7. EAST 40.16' FENCE LINE
6. WEST 6.45' 3" MAPLE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-1 FD. CHARL. CO., MON NO DIRECT TIE TO GLO
4. S40E 9.09' 5" MAPLE
5. N45W 17.28' 16" MAPLE
6. WEST 6.45' 3" MAPLE
7. EAST 40.16' FENCE LINE

Charlevoix Co. Surveyor
APPROVED
Signature *Wayne E. Boss*
Date: *Nov. 13, 1996*

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-1 & L-13 L-1 T32N-R7W CORNER COMMON TO L-13 T33N-R7W
CHARL. CO. MON.FD.
4. S40E 9.09' 5" MAPLE (NEW SPIKE & TAG SET AT 9.25')
5. N45W 17.28' 16" MAPLE (NEW SPIKE & TAG SET AT 17.06')
6. WEST 6.45' 3" MAPLE
7. EAST 40.16' FENCE LINE
8. WEST 31.72' 10" MAPLE SPIKE & TAG SET
9. S10E 21.18' 12" MAPLE SPIKE & TAG SET

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

igned by

Surveyor's Michigan License No.

Date

11/29/96

84

LIBER 003

PAGE 84



This showing has been entered
on the back of the survey