SURVEY & REMONUMENTATION

STATE OF MICHIGAN COUNTY OF CHARLEVOIX RECEIVED FOR FERDING

OPT 1 0 1006

96 DCT 10 AM 11:35

AP 1 T 8 1939	LAND CORNER RECORDATION CERTIFICATE	0 22 1
COMMISSION For corners in	Filing Requirement of Act 74, Mich. P.A. 1970	REGISTER OF DEEDS
	d In: Corner Code #	
CHARLEVOIX Locate (County)	UII.	:
1. Public Land Survey T32	2N R 6W (L-13)	
Т <u>З</u> : Т	IN R 6W L-1	
T_	R	
in Section ST_		
3. Miscellaneous S T Property in Sec. S T	R	Register of Deeds Stamp & File Number
Troporty in door		Register of Deeds Stallip & File Number
4. Lot No, Recorded Plat	<u> </u>	ABCDEFGHIJKLM 1
5. Private Claims		2 - 6 - 5 - 4 - 3 - 2 - 1 - 1
•	• •	3 10 10 11 12
I, Arthur R. Ranger , in a field survey on	May 18 , 1995 do hereby state that under	5
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the		6 18 17 16 15 14 13
United States Department of the Interior, Bureau of that the corner points mentioned in lines 3, 4 and 5	Land Management or by a decree of a Court of Law and /or because the conformance with the rules of the Michigan	7
Board of Land Surveyors or by a Decree of a recovered, found as expressed below:	Court of Law; established, re-established, monumented,	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the sai	me town and range, may be recorded	10 30 29 28 27 26 25
on this certificate.		11
		12 31 32 33 34 35 36
A. Description of original monument and acc	cessories and/or subsequent restoration:	
	T.32N-R.6W & Section 1, T.31N-R.6W er in his Resurvey and witnessed; Beech 24" N44° d witnessed corner- Sugar 18" S56°W 64.5 lks.; S	
	I" IP in road intersection and witnessed: F.E. post 56°W 56.97'	S2°W 81.5'; 30" Maple West 174.5';
B. Description of corner evidence found and	d/or method applied in restoring or reestablishing corner	:
L-13 ½ corner common to Section 36, 7 1995- Arthur R. Ranger, Surveyor found corners. The road intersection was	<u>.32N-R.6W & Section 1, T.31N-R.6W</u> a 1" IP at the road intersection; Intersection is most obviously determined from a survey, probably the	re or less on a true split between section e one mentioned above and dated 1890.
	accessories established to perpetuate locating the position	on of the corner:
<u>13 ¼ corner common to Section 36, T</u> Replaced with a Charlevoic County mon	<u>.32N-R.6W & Section 1, T.31N-R.6W</u> ument	Charlavoix Co. Surveyor
⊃.P. N47°W 56.95' ₹" R. Pine S48°W 21.62'		APPROVED
B" W. Pine \$24°W 15.13' B" Cherry \$44°E 30.82'		APPROVED Signatura May C. Fernal Data: Queba La 1996
The collateral evidence is strictly local in	nature, and is accepted as the best available evid	ence of the position of the original corner
≡igned by AM K. K.	aug or Date (D)	109 196
Surveyor's Michigan License No	31601	
•	and the second second	
	FORM APPROVED BY MICH	IGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN28, 1971
	ARTHUR R. RANGER	REVISED MAY 14, 1975 REVISED JAN., 1963 REVISED OCT., 1985

ARTHUR R. RANGER

PROFESSIONAL SURVEYOR No. 31601