

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Charlevoix

(County)

Located In

Corner Code #

1. Public Land Survey	T	33N	R	5W	K-4
	T	33N	R	5W	K-5
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on July 24, 2002 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-4 G.L.O. C. W. Cathcart August 1841 set quarter section post. Wit: Hemlock 8" S60°E 11 links
Maple 4" N67°W 22 links

K-5 G.L.O. C. W. Cathcart August 1841 set corner post. Wit: Sugar 12" S80°E 5 links
Sugar 6" N80°W 15 links

Liber 2, Page 170 Arthur Lennox P.S. #20357 October 1983 Found 1 ¼ pipe.

Wit: 24" double maple N50°W 19.0'
36" Maple cluster S10°W 25.1'
8" Birch S75°W 51.2'

Liber 2, Page 125 Carl F. Roser R.L.S. #12028 Found a 1" Pipe with a broken off monument cap November 1981.

Wit: 20" Maple S65°E 154.10'
Power Pole S25°E 63.65'
Power Pole S30°W 61.00'

Liber 4, Page 60 Ronald Brand P.S. #43046 November 2001 Found 1" pipe.

Wit: 18" Birch S75°W 51.03'
18" Maple clump S11°W 25.16'
10" Maple N63°W 16.95'
16" Triple Maple S83°E 75.8'

Liber 2, Page 170 Arthur Lennox P.S. #20357 October 1983 Found 1" pipe Wit: "T" iron S45°W 46.53'

Utility Pole S25°W 61.0'
Utility Pole S30°W 63.15'

Liber 4, Page 61 Ronald Brand P.S. #43046 2001 Found 1" pipe. Wit: Power Pole N38°W 47.25'

Power Pole S45°W 47.20'
Power Pole S28°E 46.95'
CIR #37282 N45°E 45.82'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-4 Found 1 1/4" Pipe

K-5 Found 1" Pipe fitting C.F. Roser's survey in section 14.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-4 Found 1 1/4" Pipe

Wit: 3" Maple N85°W 27.47'
8" Maple N21°W 17.12'
16" Maple Clump S14°W 25.19'
12" Maple Clump S83° E 75.75'
Blue Carsonite Post North 1'±
Centerline Padgett Rd East 30'±

K-5 Found 1" pipe

Wit: P. Pole N33°W 47.24'
P. Pole S51°W 47.10'
26" Twin Basswood S11°E 62.06'
P. Pole S34°E 47.02'

Signed by:

Carl T. Kiiskila

Date:

12-23-02

Surveyor's Michigan License No.:

33981

