SURVEY & REMONUMENTATION

JAN 2 6 1998

STATE OF MICHIGAN COUNTY OF CHARLEVOIX RECEIVED FOR

97 DEC 16 AM 10: 09

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Charlen M. Carlin

CHARLEVOIX (County)		REGISTER OF DEEDS											
1. Public Land Survey	T33N R6W T 32NR 6W T R T R	MC34/3 EAST MC34/3 5:DE OTHER #2											
2. Property Controlling S in Section S S S Property in Sec.	TR TR TR TR	**************************************	Register of Deeds Stamp & File Number										
4 Lot No Recorded Plat													
4. Lot No, Recorded Plat 5. Private Claims			1	A	В	C E	E	FC	3 H	1	J	K	<u>L</u>
· · · · · · · · · · · · · · · · · · ·			2	<u>.</u> _	6—	- !	;	- ļ	-	-	2		-
			3	3 	-		-		_				+
		a field survey on NOV. 05.	4	-	-		-	_	-1	n_	—ı¦ı	-	-12-
, 19 <u>97</u> do hereby state that under rementioned in lines 1 and 2 above were in co.				\vdash	+	\vdash				-	\dashv	\dashv	+-
current manual of survey instructions of t Management or by a decree of a Court of Law	the United States Depart	tment of the Interior, Bureau of L	and 6		18—	-1	7+	—1 ['] 6——	1	5—	14	-	13
were in conformance with the rules of the Mic	chigan Board of Land Sun	veyors or by a Decree of a Court of I	Law; '		<u> </u>			1_			丁		+
established, re-established, monumented, rec	xoverea, rouna as express	ea below;	8		19 	— ²	$^{\circ}$	_21	2	2	23 	`	-21
NOTE: Not more than 2 corners, all in t	he same town and rang	ge, may be recorded	9	ĺ	30	2		28	2	,	—26		25
on this certificate.			1:	1	<u> </u>						26 		
			1:		 31	3	2.	33	3	4	35		-36
			1;	<u>_</u>									
 A. Description of original monument at MC34/3 T.33N., R.6W. & T.32N., R.6W 1839-John Hodgson set a post on the E 20 lks; Pine 6" S18°E 16lks. 1877-E.K. Robinson found the old post 1905-E.A. Robinson shows the location 19 The meander corners position wa 19_ The Mary Feindt meander corner 1995-John Korr, surveyor found and us Condominium. 	V on the East side of Last margin of lake and in a survey of the North of the meander corners perpetuated by Mary was found and perpetuated by was found and perp	ake. d witnessed: Cedar 18" N66°E th line of Sec. 3 er on his Plat of E. S. Johnson's Feindt, surveyor. uated on a drawing by Sherm C	Chamberla	ain, s	surve	eyor.							
B. Description of corner evidence four MC 34/3 T.33NR.6W. & T.32N R.6W. On		ied in restoring or reestablishing	g corner:										
The corner was found to have been destroyed. The meander corner was reestablished by us. His sketch was a perpetuation of the corners.	sing the information from the	he sketch prepared by Sherm Chan				, sur	/eyor.						
C. Description of monument for corner MC 34/3 T.33N, R.6W. & T.32N., R.6W. On			-					Č.	d 1.M3	101			
Set 1/2" rod in curb w/cap.								. Sui VE		YV1			
N.W. corner of elec. Box S20°E 29.45' cl m.h. S24°W 13.00' M.H. S79°W 66.90' Hyd. N31°E 98.45'			Sign	Signature May C. Feln'dt Date: 12-11-97									
AND IS ACCEPTED AS A CAREFUL A	ND FAITHFUL PERP	ETUATION OF THE POSITIO	N OF THE	E OF	RIGI	NAL	COF	RNER	•				
Signed by A	· long	Date	11/12/	/97									
Surveyor's Michigan License No	31601												



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN., 1983
REVISED OCT., 1995