

# SURVEY & REMONUMENTATION

FEB 22 2001

STATE OF MICHIGAN  
COUNTY OF CHARLEVOIX  
RECEIVED FOR RECORD

00 DEC 21 AM 9:08

## SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Charlevoix

(County)

Located In:

Corner Code #

1. Public Land Survey

T 33N R 8W

C-7

T R

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous

S

T R

S

T R

Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

I, Wayne E. Boss, in a field survey on November, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-7 October 22, 1841 Charles W. Cathcart D.S.

Set post

1) Beech 10" N40° W 24 links (15.84')

2) Beech 6" S16° E 32 links (21.12')

November 1980 N.B. Deyoung P.S.

Found 1" pipe in C.L. N-S road with fences East and West

3) 10" Bass wood N 15° W 42.63'

4) 10" Ash N60° E 33.86'

5) 10" Maple N83° W 40.30'

6) 12" Ash N70° W 26.85'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-7 Found 1" pipe in C.L. N-S road and old fence to East, also found remains of wood post 1 1/2' below surface  
10" Maple N 83° W 40.30' found nail

C-8 to C-7 GLO 40 chains (2640') measures 2642.69'

C-7 to D-7 GLO 40.10 chains (2646.6') measures 2633.89'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-7 Placed Charlevoix County steel marker

5) 10" Maple N 83° W 40.30' found nail

7) Power pole N43° W 44.93' set nail and tag

8) 8" Maple N37° E 68.15' placed nail

9) 12" Maple N79° E 40.28' placed nail

Charlevoix Co. Surveyor

APPROVED

Signature Mary C. Ferrell  
Date 12/22/00

And is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by

Date

Surveyor's Michigan License No.

