

SURVEY & REMONUMENTATION

FEB 22 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

00 DEC 21 AM 9:07

Charles W. Jost
REGISTER OF DEEDS

For corners in

Charlevoix
(County)

Located In:

Corner Code #

1. Public Land Survey

T 33N R 8W D-7

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Wayne E. Boss, in a field survey on November, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D-7 October 22, 1841 Charles W. Cathcart D.S.

Set 1/4 post

1) Hemlock 24" N 30° W 18 links (11.88')

2) Beech 4" S30° E 18 links (11.88')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found existing fence intersection

Older fence to West

Newer fence to North and East

C-7 to E-7 E 5273.783'

C-7 to D-7 GLO 40.10 chains (2646.6') measures 2633.89 existing fence intersection

D-7 to E-7 GLO 40.10 chains (2646.6') measures 2639.97'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-7 Placed Charlevoix County steel marker.

3) Fence post East 0.44' Placed Nail

4) 6" Cedar S 72° E 75.93' Placed Nail

5) 4" Apple S 15° W 13.44' Placed Nail


6) 6" Cedar S 77° W 12.88' Placed Nail

Charlevoix Co. Surveyor
APPROVED
Signature Mary C. Feenolt
Date 12-22-00

And is accepted as a careful and faithful reestablishment of the positive of the original corner.

Signed by *Wayne E. Boss*
Surveyor's Michigan License No. 2638

Date 12/15/2000



	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													