

FEB 22 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Charlevoix
(County)

Located In:

Corner Code #

1. Public Land Survey T 33N R 8W E-7
T R
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Wayne E. Boss, in a field survey on November, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- E-7 October 22, 1841 Charles W. Catheart, D.S.
Set post
1) Sugar 24" S50° E 20 links
2) Hemlock 36" N 20° W 10 links

- July 9, 1965 Ben Seifert, P.S.
Found 1 1/2" bent pipe, previously used in 1950
Re-set with Charlevoix County marker
3) Flag pole 320° 99.2'
4) NE corner church foundation 210° 33.4'
5) Old hand pump 52° S7.0'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- E-7 November 6, 2000
Found 1" o.d. pipe in surface of asphalt 3' North of South edge
1" o.d. pipe pinned into 1 1/2" pipe 15" below surface next to 12" to 14" rock.
3) SE corner flag pole N 40° W 99.2'
4) NE corner church foundation S30° W 33.4

- D-7 to E-7 GLO 40.10 chains (2646.6') D-78 existing post
E-7 to E-6 GLO 40.00 chains (2640') E7 to new E6 2654.615'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- E-7 pipe assemble still in place placed monument box at surface
3) SE corner flag pole N 40° W 99.2'
4) NE corner church foundation S 30° W 33.4'
5) Guard post N 48° E 67.42' placed nail
6) Power pole S 55° E 62.48' found nail

And is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by

Surveyor's Michigan License No.

Date

12/15/2000

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

00 DEC 21 AM 9:06

Charlene M. Justing
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													