

Cheboygan County Remonumentation Corner
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Cheboygan
(County)

Located In

Corner Code #

1. Public Land Survey	T	33N	R	2W	M-5
	T				
2. Property Controlling in Section	S	T		R	
	S	T		R	
3. Miscellaneous Property in Section	S	T		R	
	S	T		R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on July 22, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

M-5 – Sec. Cor. comm. to sec.'s 12 & 13, T33N, R2W &
sec.'s 7 & 18, T33N, R1W

1840 – GLO – John Mullet – Set post corner sec.'s 12, 13

Fir 8" N54°E 14 links

Spruce 8" S42°W 5 links

1956 – Survey Map – Thomas F. Schweigert, P.S.#6525 – Fd. 1 1/4" pipe.

Also old stake. Set mon. for corner. Steel fence post S45°E 33.00';

Steel fence post N45°E 33.00'

1962 – L.C.R.C. – L.A, p.59 – Dean C. DeLamater, P.S.#5778 – Replaced

old 1 1/4" pipe w/conc. mon. w/ 1/2" bar. Same wits. as 1956.

1973 – L.C.R.C. – L.1, p.93 – Delmer E. Porter, P.S.#15410 – Fd. 4" conc.

mon. w/RLS cap#6525 in N-S line & steel posts w/wits. Steel fence

post S60°E 16.77'; Steel fence post N45°E 16.43'; 4" Dead Cedar

S60°W 3.67'

1993 – L.C.R.C. – L.10, p.38 – Richard C. Dunn, P.S.#12020 – Fd. 4" conc.

w/R.L.S. cap#6525 as recorded in L.A, p.59 & L.1, p.93. Steel Fence

Post S60°E 16.77'; Steel Fence Post N45°E 16.43'; Steel Fence Post

N45°W 16.45'; Steel Fence Post S45°W 16.45'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

M-5 – Sec. Cor. comm. to sec.'s 12 & 13, T33N, R2W &
sec.'s 7 & 18, T33N, R1W

Found concrete monument w/ stamped 3 1/2" alum. cap leaning badly to the NW by 0.75' and sticking out of the ground by 2.5'. Accepted found monument as a careful and faithful reestablishment of the position of the original corner. Found no other evidence to dispute the position for the corner. Reset conc. monument to a vertical position and lowered so that 1" of the monument is above ground. Fence running North, West and South from corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5 – Sec. Cor. comm. to sec.'s 12 & 13, T33N, R2W &
sec.'s 7 & 18, T33N, R1W

4" dia. x 4' long conc. mon. w/ 3 1/2" dia. stamped alum. cap

Witnesses:

N40°E 24.40' to set N&T on SE side 5" B. Spruce

*N45°E 16.41' to top of metal fence post

S70°E 23.41' to set N&T on S side 5" B. Spruce

*S44°E 16.80' to top of metal fence post

*S50°W 16.27' to top of metal fence post

S64°W 24.38' to set N&T on SE side 4" B. Spruce

*N32°W 16.85' to top of metal fence post

Set Blue Carsonite Post 1' East * Previous witness of record.



Signed by:

Carl T Kuskila

Date:

8-17-11

Surveyor's Michigan License No.:

33981