

Cheboygan County Remonumentation Corner
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Cheboygan _____ Located In _____ Corner Code # _____
(County)

1. Public Land Survey	T	33N	R	2W	M-6
	T	_____	_____	_____	_____
2. Property Controlling in Section	S	T	_____	R	_____
	S	T	_____	R	_____
3. Miscellaneous Property in Section	S	T	_____	R	_____
	S	T	_____	R	_____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on July 14, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4			3		2	1
3													
4	7			8			9			10		11	12
5													
6	18			17			16			15		14	13
7													
8	19			20			21			22		23	24
9													
10	30			29			28			27		26	25
11													
12	31			32			33			34		35	36
13													

Register of Deeds Stamp & File Number

A. Description of original monument and accessories and/or subsequent restoration:

M-6 – Quarter Corner comm. to section. 13, T33N, R2W & section 18, T33N, R1W

1840 – GLO – John Mullet – Set Quarter sec. post.

Beech 12" N20°W 24 links

Beech 6" S54°E 21 links

1993 – L.C.R.C. – L.10, p.39 – Richard C. Dunn, P.S.#12020 – Est. cor.

midway between the NE & SE corners of sec. 13, T33N, R2W. Set 5/8"

x 30" iron rod & 3" remon cap. 30" Twin Ash N06°W 36.78';

10" Maple S15°E 35.44'; 16" Oak S79°E 84.92'; 6" Maple N33°E

68.85'

2008 – Working drawing Survey Map – Ronald C. Brand, P.S.#43046 –

Traversed along East side of sec. 13, shows distances N&S of corner.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

M-6 – Quarter Corner comm. to section. 13, T33N, R2W & section 18, T33N, R1W

Found 3" dia. stamped aluminum cap on 5/8" rod per L.C.R.C., L.10, p.39 59' West of N-S two-track road. Accepted found cap and iron as a careful and faithful reestablishment of the position of the original corner. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-6 – Quarter Corner comm. to section. 13, T33N, R2W & section 18, T33N, R1W

Stamped 3" dia. aluminum cap on 5/8"x30" rebar

Witnesses:

S60°E 12.65' to set N&T on S side 5" B. Fir

*S16°E 35.36' to fd, N&T on W side 12" S. Maple

S88°W 17.67' to set N&T on N side 5" B. Fir

*N05°W 36.70' to set N&T on W side 18&20" Twin Ash

Set Blue Carsonite Post 1' North

* Previous witness of record.



Signed by:

Carl T. Kiiskila

Date:

8-17-11

Surveyor's Michigan License No.:

33981