

# SURVEY & REMONUMENTATION

MAY 1997

## COMMISSION

For corners in

Cheboygan

(County)

Located In:

Corner Code #

1. Public Land Survey

T 34N R 1W

M-3

T R

T 34 R 1E

MA-3

T R

S T R

S T R

S T R

S T R

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Brian K. Fullford, in a field survey on August, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O.

Set Section Corner

8" Beech S31°W 9 Links

7" Beech N12°E 18 Links

1951 D.O.C. Corner Record

Dean DeLamater #5778

Set 1" Pipe w/4" Brass Cap

8" H. Maple N70°W 26 Links

7" H. Maple S33°E 103 Links

1973 Recorded Survey

Liber 343, Pages 450 & 451

Delmer Porter #15410

Fnd Conservation Monument

8" H. Maple N80°E 21.30'

12" H. Maple N65°W 16.22'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fnd 1" Pipe With Department of Conservation Brass Cap

Fnd 8" H. Maple N71°W 17.03' (DeLamater Witness)

Fnd 8" H. Maple N83°E 21.50' (Porter Witness)

Fnd 5" Maple S66°W 2.05' (Porter Tag)

LIBER 010 PAGE 205

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-3 Fnd 1" Pipe with 4" Department of Conservation Brass Cap. Accepted as a careful & faithful re-establishment of the position of the original corner.

21" Maple N40°E 23.90' Set Tag

9" Maple Clump N83°E 21.90' Set Tag

5" Maple S66°W 2.05' Tag #15410

8"/12" Tw. Maple N71°W 17.03' Set Tag

THIS CORNER IS ALSO DESIGNATED AS CORNER CODE #A-3, IN T34N-R1E.

Signed by

Surveyor's Michigan License No. 41099  
Brian K. Fullford, PS

Date

10/22/96

RECEIVED FOR RECORD

96 NOV 25 PM 1:03

*Joanna Spray*  
CLERK/REGISTER  
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

