

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N.R. 1 E


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to sections 28, 29, 32, and 33

CORNER MONUMENT Set 1" pipe with 1/4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED December 13, 1965

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

10" Cedar S3E 69.0

8" Cedar S88W 44.4

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established while making a survey of Sections 21 and 28.  
Set corner on line over 1/4 and section corner east at double distance  
of east 1/2 mile. Fence lines and occupation seem to support this method.  
Could find no evidence of previous corner. Checks okay to 1/4 corner north.

SURVEYOR'S SEAL

SIGNED Kenneth Wetting  
REGISTERED LAND SURVEYOR #10068

DATE December 30, 1965