

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Cheboygan Located In \_\_\_\_\_ Corner Code # \_\_\_\_\_  
(County)

1. Public Land Survey T 34N R 1W L-4  
T 34N R 1W L-5

2. Property Controlling in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous Property in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on February 3, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

L-4 - Center 1/4 Corner, Section 12, T34N,R1W

None

L5 - 1/4 Corner comm. to sec.'s 12&13, T34N,R1W

1850 - GLO - Austin Burt - Set 1/4 sec. corner.

Hemlock 12" S20°E 26 Links

Hemlock 10" N17°E omitted

1966 - Land Corner Record - MDOC - Kenneth J. Ostling, P.S.#10068 -

L.A. p.167 - This corner was fd. during a survey in this township. Fd. 1" pipe and squared stake as set by unknown surveyor. Remnants of U.S. witness in place, & fits well w/stream east & occupation west. Set 1" pipe w/4" aluminum cap.

5" R. Maple S14°E 23.2'

16" Elm N24°W 70.7'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

L-4 - Center 1/4 Corner, Section 12, T34N,R1W

Set stamped 2" dia. alum. cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

L5 - 1/4 Corner comm. to sec.'s 12&13, T34N,R1W

Found DOC monument up 0.5' above ground per 1966 Land Cor. Record - L.A. p.167. Accepted found DOC monument as a careful and faithful perpetuation of the position of the original corner. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-4 - Center 1/4 Corner, Section 12, T34N,R1W

Stamped 2" dia. aluminum cap on 5/8"x34" rebar

L5 - 1/4 Corner comm. to sec.'s 12&13, T34N,R1W

Stamped 4" dia. aluminum cap on 1" galvanized pipe

Witnesses:

N40°E 9.81' to set N&T on W side 7" R. Maple Clump  
S68°E 14.58' to set N&T on S side 10" R. Maple  
S57°W 11.55' to set N&T on E side 6" Twin R. Maple  
N20°W 26.47' to set N&T on S side 6" Twin R. Maple  
Set Blue Carsonite Post w/location tag 1' North

Witnesses:

N46°E 19.61' to set N&T on N side 12" W. Pine  
\*S23°E 24.55' to set N&T @ old N&T on E side 11" S. Maple  
S21°W 44.14' to set N&T on NW side 19" S. Maple  
N79°W 45.35' to set N&T on NE side 9" W. Pine  
North 39' to C/L E-W 2-track  
Set Blue Carsonite Post 1' North  
\* Previous witness of record.

Signed by:

Carl T Kiiskila

Date:

6-15-10

Surveyor's Michigan License No.:

33981

