

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Cheboygan  
(County)

Located In

Corner Code #

1. Public Land Survey	T	34N	R	1W	M-4
	T	34N	R	1W	M-5
2. Property Controlling in Section	S	T		R	
	S	T		R	
3. Miscellaneous Property in Section	S	T		R	
	S	T		R	

Register of Deeds Stamp & File Number

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on February 1, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

M-4 - ¼ Corner comm. to sec.12, T34N,R1W & sec.7, T34N,R1E

M5 - Sec. Cor. comm. to sec.'s 12&13, T34N,R1W & sec.'s 7 & 18, T34N, R1E

1840 - GLO - John Hodgson/John Mullet - Set ¼ sec. post.

Spruce 8" S44°E 8 Links

Hemlock 7" S42°W 9 Links

1966 - Land Corner Record - MDOC - Kenneth J. Ostling, P.S.#10068 -

This corner was established by prop. measurement. No evidence of any previous corner. Set 1" pipe w/4" aluminum cap.

16" W.Spruce N69°W 44.2'

9" Balsam N19°E 26.0'

1996 - Remon L.C.R.C - L.10,p.206 - Brian K. Fullford, P.S.#41099 - Fd.

1" pipe w/4"DOC cap. Accepted as a careful and faithful reestablishment of the position of the original corner. 3" Balsam N80°E 5.60'; 4" Balsam S35°E 7.12'; 6" Balsam S67°W 6.60'; 6" Balsam N46°W 4.24'

+/- 200' South of Milligan Creek.

1840 - GLO - John Hodgson/John Mullet - Set post cor. sec.'s 1 & 12

Hemlock 10" N16°E 19 Links

Hemlock 7" S66°W 8 Links

1966 - Land Corner Record - MDOC - Kenneth J. Ostling, P.S.#10068 -

This corner was fd. during a survey in the area. Set cor. at point of old stake, scribed & squared, set by unknown surveyor. Fits well w/U.S. notes to swamp edge east, ¼ cor. west & sec. cors. N & S. Set 1" pipe w/4" aluminum cap. 16" W.Spruce N69°W 44.2'; 9" Balsam N19°E 26.0'

1996 - Remon L.C.R.C - L.10,p.207 - Brian K. Fullford, P.S.#41099 - Fd.

1" pipe w/4"DOC cap. Accepted as a careful and faithful reestablishment of the position of the original corner. 12" R. Pine N10°E 26.63'; 5" W. Pine S86°E 18.63'; 5" R. Pine S31°W 15.03'; 10" Aspen N62°W 7.96'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

M-4 - ¼ Corner comm. to sec.12, T34N,R1W & sec.7, T34N,R1E

M5 - Sec. Cor. comm. to sec.'s 12&13, T34N,R1W & sec.'s 7 & 18, T34N, R1E

Found DOC monument 1' above ground, per 1966 Land Cor Record by Ostling. Corner falls is ± 250' south of south bank of Milligan Creek. Accepted found DOC monument as a careful and faithful reestablishment of the position of the original corner. Found no other evidence to dispute the location for the corner.

Found DOC monument up 0.5' above ground per 1966 Land Cor. Record by Ostling. Accepted found DOC monument as a careful and faithful reestablishment of the position of the original corner. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-4 - ¼ Corner comm. to sec.12, T34N,R1W & sec.7, T34N,R1E

M5 - Sec. Cor. comm. to sec.'s 12&13, T34N,R1W & sec.'s 7 & 18, T34N, R1E

Stamped 4" dia. aluminum cap on 1" galvanized pipe

Stamped 4" dia. aluminum cap on 1" galvanized pipe

Witnesses:

\*N84°E 5.77' to set N&T on N side 5" B. Fir  
S11°E 33.88' to set N&T on E side 5" B. Fir (scribed 'XBT')  
S67°W 36.80' to set N&T on N side 6" R. Maple (scribed 'XBT')  
N52°W 37.87' to set N&T on NE side 8" B. Fir (scribed 'XBT')  
Set Blue Carsonite Post 1' North

\* Previous witness of record.

Witnesses:

\*N08°E 26.57' to set N&T @ old N&T on E side 14" R. Maple (scribed 'XBT')  
\*N88°E 18.60' to set N&T on N side 10" W. Pine (scribed 'XBT')  
\*S27°W 15.13' to set N&T on SE side 9" R. Pine (scribed 'XBT')  
N81°W 17.63' to set N&T on N side 3" R. Pine  
\*N56°W 7.88' to fd. N&T on NE side 11" Aspen  
\*N08°E 22.92' to fd. notch & scribe in 8" W.P.S.  
Set Blue Carsonite Post 1' North  
\* Previous witness of record.

Signed by:

Carl T Kiiskila

Date:

6-15-10

Surveyor's Michigan License No.:

33981

