

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N. R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 27-28

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED June 17, 1966

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

40" W. Pine stump N 78 E 61.5'

7" S. Maple S 32 W 33.5'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a retracement in this township. Found $1\frac{1}{2}$ " pipe at corner as established by Schaaf in 1930s. Possible USBT sites. Falls good for midpoint between corners, but somewhat off line. Buried $1\frac{1}{2}$ " pipe with our corner.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Osting* DATE June 20, 1966
REGISTERED LAND SURVEYOR #70068