MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_34 NR 1 E

			Chebaygen COUNTY
DESCRIPTION	OF	CORNER	-Section Corner common to Sections 1,12,6,7
DESCRIPTION	OF	CORNER	MONUMENT_1# Pipe with 4" Brass cap
WIT TNESSES	то	CORNER	8t H. Maple - N. 70 N 26 Vinks
			75 H. Maple - S 33 E = 103 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by proportionate measurement, by Forestry Division survey crew, while working in this area. Burned over land, no positive identification.

Cormer was placed and witnessed November 9, 1951.

SURVEYORS SEAL

SIGNED SIGNED DATE 12/6/51_
REGISTERED LAND SURVEYOR