

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Cheboygan

(County)

Located In

Corner Code #

1. Public Land Survey

T 34N R 3W D-1

2. Property Controlling  
in Section

S 5 T R

3. Miscellaneous  
Property in Section

S T R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on April 22, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

D-1 Richard Dunn P.S.#12020 set a 1/2" bar with P.S. Cap  
#12020 for the North 1/4 corner of section 5.

Brian Fullford P.S.#41099 found a 1/2" bar as set by  
R. Dunn

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

D-1 Found a 1/2" bar fitting R. Dunn's and B. Fullford's survey  
in section 5.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-1 Set standard DNR monument in place of found 1/2" bar

Wits: N&T SW side 5" Maple	N38°W	27.51'
N&T E side 7" Maple	N01°E	14.92'
N&T S side 4" Maple	S80°E	17.05'
N&T E side 3" Apple	S11°E	17.43'
Remon Monument	N84°W	2.88'
N-S Fence	West	5.2'



Signed by:

Carl T. Kiiskila

Date:

8-18-08

Surveyor's Michigan License No.:

33981