

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 34 N.R. 1 W
T. 35 N.R. 1 W Cheboygan COUNTY

DESCRIPTION OF CORNER Sec. corner common to Sections 1, 2, 35, 36

CORNER MONUMENT Set 1" pipe with 1/4" Aluminum cap

DATE MONUMENT PLACED AND WITNESSED July 7, 1965

WITNESSES TO CORNER..... 10" Beech S 25 W 22.6'



7" Maple N 40 E 39.2'

1" Iron Pipe N 81 E 22.4'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set while making a survey in this township. Placed corner on line over, and equidistant from 1/4 and section corners east. This makes miles of sections 35 and 34 very nearly equal and conforms more closely with present occupation and a proper survey pattern. The 1" pipe noted above was apparently intended to be placed as we set our corner, but hilly terrain in W 1/2 of Section 36 created shortage in measurement. Believe ours to be more fitting restoration of this corner.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE October 18, 1965
REGISTERED LAND SURVEYOR #10068