

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 35 N. R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER M.C. corner common to Sections 34-35 on S side of Stony Creek Flooding

CORNER MONUMENT Set 1" x 2 1/4" pipe and post

DATE MONUMENT PLACED AND WITNESSED June 16, 1966

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

BT 6" S. Maple N 61 E 59.5'

BT 20" W. Pine Stump S 71 E 66.3

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set to identify true section line and witness theoretical section corner which falls in flooded area.

Corner is 7.00 ch. south of section corner in lake.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE June 20, 1966
REGISTERED LAND SURVEYOR #10068