## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_\_35. NR\_\_2\_W\_,T 36 NR 2 W

			Chahoygan COUNTY
DESCRIPTION	OF	CORNER	Section_Corner common to Sections 1,2,35,36
DESCRIPTION	OF	CORNER	MONUMENT_1% Pipe with 4%_Brass cap
WITTNESSES	то	CORNER	R* Aspen = H 65_W = 74 Links
			10* J. Pine 8_23 W - 281 Links
			12" J. Pipe - S 72 F - 227 Links
			•

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was located by the Forestry Division survey crew, while working in this area. One original B.T. still in place, in good condition.

Corner was placed and witnessed June 4, 1951.

SURVEYORS SEAL

SIGNED LEAN SURVEYOR DATE 7/25/51