

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Cheboygan
(County)

Located In

Corner Code #

1. Public Land Survey T 35 N R 2 W B-11
T
2. Property Controlling in Section S 31 T 35N R 2W 7
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on July 18, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	8		6		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11	●												
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-11 G.L.O. Harvey Mullen D.S. 1855
Set quarter section post
Wit: Spruce Pine 10 N35°E 49 links
Spruce Pine 10 S03°E 55 links

7 This corner position was not established during the original government survey.

Norman Caldwell RLS #12018 Dec. 1960
Set steel spring leaf at proportionate distance and online between section corners.
Wit: Due South 124.24' 12" Jack Pine, S50°E 101.43' 10" Jack Pine

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

B-11 Found 1/2" X 4" steel leaf spring

7- Established the Southeast corner of the Northeast quarter for the Northeast quarter of section 31 per B.L. M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-11 Left 1/2" X 4" steel leaf spring in place
Wit: *14" Red Pine S40°W 31.81'
*12" Red Pine S23°E 65.21'
*14" Red Pine East 44.38'
*12" Aspen N56°W 58.63'

7- Set 5/8" X 32" rerod with P.S. cap #33981
Wit: 28" Spruce S66°E 5.13'
3" Spruce S07°W 23.77'
5" Spruce N77°W 8.52'
4" Spruce N21°E 10.86'

* Old witnesses by P.S. #41099 Brain K. Fullford

Signed by:

Carl T. Kiiskila

Date:

1-10-02

Surveyor's Michigan License No.: 33981

