

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Cheboygan

(County)

Located In

Corner Code #

1. Public Land Survey

T 35N R 2W K-2  
T 35N R 2W I-2

2. Property Controlling  
in Section

S T R  
S T R

3. Miscellaneous  
Property in Section

S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on July 18, 2002 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-2 G.L.O. Harvey Mullen 1855

Set quarter section post

Wit: Spruce Pine 10 N6.5°E 23 links

Spruce Pine 10 N78°W 32 links

I-2 G.L.O. Harvey Mullen 1855

Set quarter section post

Wit: Hemlock 12 N57.5°E 32 links

Hemlock 10 N19°W 22 links

Liber A, P. 392 Kenneth Larsen filed a corner record for Kenneth J. Ostling R.L. S. #10068 January 1965, who reestablished the East quarter corner of section 2 by proportionate measurement.

Wit: 8" J. Pine N60°E 56.1'

8" J. Pine S15°W 16.5'

Liber A, P. 391 Kenneth Larsen filed a corner record for Kenneth J. Ostling R.L.S. #10068, September 1965, who reestablished the West quarter corner of section 2 by proportionate measurement.

Wit: 5" Maple N26°E 17.7'

5" Balsam S88°E 18.8'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-2 Found DNR monument slightly bent from road grading. Set the original department of conservation brass cap on a new 1" X 48" pipe.

I-2 Found DNR monument as set by Kenneth J. Ostling.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-2 Set 1" pipe with 4" brass cap

Wit: 12" J. Pine S21°W 16.77'

6" J. Pine N41°W 17.24'

5" J. Pine N52°E 35.25'

5" J. Pine S37°E 41.19'

Ctr. N-S two track East 8'

I-2 Found 1" pipe with 4" brass cap

Wit: 7" Maple N41°E 8.60'

6" Balsam S87°E 19.26'

5" Maple S27°W 18.76'

15" Poplar S67°W 9.7'

Signed by:

Carl T. Kiiskila

Date:

7-17-02

Surveyor's Michigan License No.:

33981

