1997 CHEBOYGAN COUNTY, STATE OF MICHIGAN REMONUMENTATION

FEB 2.6 1998

LAND CORNER	RECORDATION	N CERTIFICATE
Filing Requirem	ent of Act 74, N	lich. P.A. 1970

SECTION

For corners in	1	12-22-97
CHEBOYGAN Located In: Corner Code	# RE	CEIVED FOR RECORDM
1. Public Land Survey T_35NR_3W K_ T_R T_R T_R	6	JoanneSpray
2. Property Controlling S TR		CLERK/REGISTER HUROYCAN COUNTY,MICHIGAN
Property in Sec. S T R		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims		A B C D E F G H I J K L
		3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
I, <u>Ronald Bischer</u> , in a field survey on <u>Oct 2</u> , 19 9 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned is conformance with regulations and rules therefore as required in the current manufunited States Department of the Interior, Bureau of Land Management or by a dethat the corner points mentioned in lines 3, 4 and 5 above were in conformance Board of Land Surveyors or by a Decree of a Court of Law; established, recovered, found as expressed below:	n lines 1 and 2 above were in all of survey instructions of the scree of a Court of Law and /or with the rules of the Michigan re-established, monumented,	4
NOTE: Not more than 2 corners, all in the same town and range, may be on this certificate.	e recorded	9 10 30 29 28 27 26 25
On this Certificate.		11 12 -31 -32 -33 -34 -35 -36- 13
A. Description of original monument and accessories and/or subsequ	uent restoration:	
K-6 GLO notes Harvey Mellen 1855 Resurvey Set Post 20" White pine N82 E 27 1ks 20" White Pine N09 w 11 1ks	1953 Orlando Doyle #7319 Found 1" pipe and set 3 witnesses 1962 Dean DelaMater #5778 found Con. Mon and set 2 witnesses 1982 Ronald Bischer #22428 Found Conc. Mon. and Cap #10710 1990 James Granger #16041 Found Conc. Mon. & Cap #10710	
B. Description of corner evidence found and/or method applied in re	storing of reestablishing con	ner ses
K~6		RONALD BISCHER LAND
Found Conc. Mon. and Cap #10710 found both DelaMater witnesses found Two Bischer and Granger witnesses Seb Monument box on corner and set Rem	es non cap	SURVEYOR NO. 22428
atop concrete monument	LIBER 011 PAGE 5	8 Secretarian Pallo 2 and Control of the Control of
C. Description of monument for corner and accessories established	to perpetuate locating the po	esition of the corner:
K-6 Remon cap on Concrete Monument in Mon	ument box	
N89 W 26.43' 18" Red Oak S32 W 52.01' 19" White Oak N32 W 50.30' 19" White Oak N60 W 26.09' 12" White Pine	DelaMater with DelaMater with Bischer with Granger with	tness Sharper
Signed by Roxall R. Bish. Surveyor's Michigan License No. 22428	Date	Oct. 10, 1997
Surveyors Michigan License No.		