LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Cheboygan			Located	l In	Corner Code #			
(County)								
1. Public Land Survey		T	35N	R 1E	G-3			
2. Dranady Cantrallina		ı	35N	R 1E	<u>H-3</u>			
Property Controlling in Section	S	Т		R				
111 00000011	s	T		R				
3. Miscellaneous	_							
Property in Section	s	Т.		. R				
	S	T		R				
4. Lot No:	Recorded Plat:							
5. Private Claims:								
I, <u>Carl T. Kiiskila,</u> in a fiel	d survey o	n <u>A</u>	pril 5, 20	011 do he	ereby state that under			

requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

. 1	A E	3 C		E	F	G	н	1	J	K	L	М
1			П	\neg	П	Т	Т	Т	Т	Т	Т	╗
2	⊢ €	<u> —</u>	— §	\dashv	-4.	1	- 3 —	╈	- 2 -	+	-1-	┨
3		 	-	-	-		•	+	+	+	+	\dashv
4	<u> </u>	!—	<u></u> ⊢ 8¦	\rightarrow	- a'-	+	_10_	+	-11-	+	_12	\dashv
5	\vdash		\vdash	\dashv	+	+	+	+	+	+	+	\dashv
6	<u> </u> -1	8—— İ	1	7—	-16-	+	-15 <u>-</u>	+	-14	+	-13	\dashv
7	H	\vdash	Н	\dashv	+	+	+	+	+	+	+	\dashv
8	-1		20		-21- 1	+	-22- [+	-23-	+	—2 '4 	┥
9	\vdash		\vdash	\dashv	\dashv	+	+	+	\dashv	\dashv	\dashv	ᅱ
10	-3	ģ	2	9—	—2ģ.	+	-27-	+	-26	+	25	ᅱ
11	\vdash	\vdash	\vdash	\vdash	\dashv	+	+	+	+	+	+	\dashv
12	3	<u> </u>	-3	<u> </u>	-33.	-	-34-	+	-35-	+	-36·	\dashv
13	L_		Ш									

Register of Deeds Stamp & File Number

A. Description of original monument and accessories and/or subsequent restoration:

G-3 - Section Corner comm. to sec.'s 3,4,9 & 10, T35N, R01E

1840 - GLO - Brevort- Set post cor. of sects. 3,4,9 & 10

Sp. Pine 7 N40°W 36 Sp. Pine 6 S50°E 6.3

1991 – L.C.R.C. – L.2, p.141 – Norman J. Quaine, P.S.#33984 Fd. 2 ½ " pipe at int. of firelane trails N-S & W. S52°W 34.05' 8" Oak N17°W 65.95' 10" N. Pine S44°E 51.91' 12" N. Pine

H-3 - 1/4 Corner comm. to sec.'s 3 & 10, T35N, R01E

1840 - GLO - Brevort- Set qr. Section post. W. Pine 18 S30°E 45 Aspen 10 North 21

1949 - Cheb. Co. Land Cor. Rec. - L.a, p.267 - Orlando Doyle, P.S.#7319 - Fd. wood stake, set conc. mon. 8" Cedar S47°E 28.31'; 12" Cedar S02°E 14.44'; 10" Spruce N10°W 12.35′ 1984 – L.C.R.C. – L.1, p.318 – Orlando Doyle, P.S.#7319 – Fd.

wood stake, set conc. mon. 16" Cedar S10°W 14.64'; 14" Cedar S47°E 28.24'; 12" Spruce N12°W 12.07'; 5" Cedar N76°W 20.85'

1989 – L.C.R.C. – L.2, p.96 – James H. Granger, P.S.#16041 – Fd. conc. mon. Same witnesses as above.

1996 - L.C.R.C. - L.3, p.75 - Thomas G. Hall, P.S.#41100 - Fd. 4" conc. mon. 10" Spruce Stp. N10°W 12.4'; 6" B. Fir N07°W 23.97'; 8" Cedar S47°E 28.31'; 12" Cedar S10°W 14.44'; 6" Cedar N76°W 20.78'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

usk

33981

G-3 - Section Corner comm. to sec.'s 3,4,9 & 10, T35N, R01E

H-3 - 1/4 Corner comm. to sec.'s 3 & 10, T35N, R01E

Found and accepted 2" dia. pipe with 1/2" CIR#15410 in center of pipe. Accepted as the best available evidence for the position of the original corner. Corner falls 1' West of N-S centerline of trail road and 2' South of centerline trail to West.

Found and accepted 4" dia. concrete monument per L.C.R.C. Liber a, - p.267. Accepted monument as the best available evidence for the position of the original corner. Added 1/2" plastic P.S. cap# 33981 to concrete monument. Corner falls in centerline of NE-SW overhead power line. Found no other evidence to dispute the location of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-3 - Section Corner comm. to sec.'s 3,4,9 & 10, T35N, R01E

H-3 - 1/4 Corner comm. to sec.'s 3 & 10, T35N, R01E

2" dia. pipe with 1/2" CIR#15410 in center

4" dia. conc. monument with 1/2" plastic P.S. cap #33981

Wit: N21°E 62.25' to set N&T on W side 15" J. Pine S49°E 51.86' to set N&T on SW side 17" R. Pine *S47°W 34.11' to Fd. N&T#15410 on NW side 10" Oak *N22°W 65 96' to set N&T at old N&T on NE side 13" R. Pine Wit: *N84°E 41.08' to set N&T at N&T on S side 7" B. Fir S51°E 28.11' to set N&T on NE side 16" Cedar *S05°W 14.60' to Fd. N&T on SE side 16" Cedar

*N77°W 20.80' to set N&T on SW side 9" Cedar *N42°W 23.96' to set N&T at N&T on W side 9" B. Fir OF MICHIC

* Witness of previous record. al

CARL (USKILA

LAND

Surveyor's Michigan License No.:

SURVEYOR

FORM APPROVED BY 3898 GAN TAGE FOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971
Revised May 14, 1975
Revised Jan. 1983
Revised Oct 1005