

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Cheboygan

(County)

Located In

Corner Code #

1. Public Land Survey

T

R

T

R

2. Property Controlling
in Section

S

7

T

36N

R

2W

15

S

T

R

3. Miscellaneous

Property in Section

S

T

R

S

T

R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on September 25, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

15- Found a 3/8" iron rod set by an unknown land surveyor.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

15- Found 3/8" iron rod fitting the proper B.L.M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

15- Set 1" X 12" iron pipe over found 3/8" iron rod

Wit: 11" W. Pine N47°E 80.79'

8" Twin R. Oak N36°W 66.18'

P. Pole S66°E 146.04'

P. Pole S78°W 136.14'



Signed by:

Carl T. Kiiskila

Date:

12/7/06

Surveyor's Michigan License No.:

33981