

JAN 28 1999

1998

SECTION

CHEBOYGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Cheboygan

Located In:

Corner Code #

(County)

1. Public Land Survey

T^{36N} R^{3W}

C-3

T R

T R

T R

T R

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

RECEIVED FOR RECORD 1-8-99
at 8:57 O'Clock A M

Joanne Spray

CLERK/REGISTER
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Brian K. Fullford, in a field survey on June, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3			●										
4		7		8		9		10		11		12	
5													
6		13		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1855 Harvey Mellon

Resurvey

Set post

20" Hemlock S 14° W 24 lks

18" Sugar Maple N 59° E 18 lks

Sept 1976 Herbert L. Fluharty

#18223

Set 5/8" X 18" Re-rod w/cap on

N.W. side of post-conceded 2-

way fence cor. South & East

5" Maple Cluster (no bearing

given) 48.82'

8" Maple Cluster S 65° E 18.71'

6" Cherry Cluster S 13° W

22.86'

33' ± E of Woods Road

Oct 1968 Orlando Doyle #7319

Fnd "T" Bar

P. Pole N 51° 30' E 44.15'

Fence cor. N 47° 30' W 44.75'

30" Poplar S 51° W 140.69'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fnd Conc Mon w/U of M Cap & #7319

At NW Side of Fence Post - old wit

Fence line to South & East - old wit

33' +/- East of Woods Rd.

18' +/- South of Two track to East

12" Maple Cluster S 60° E 18.57' - old wit

6" Cherry Cluster S 16° W 22.77' - old wit

7" Maple Cluster N 48° W 48.70' - old wit

James H. Hanger

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-3 Use existing concrete monument with U of M cap & RLS #7319, and position is accepted as a careful and faithful perpetuation of the original corner.

15" Poplar N 5° E 40.83' Set tag 41099

12" Maple Cluster S 60° E 18.57' Set tag 41099

6" Cherry Cluster S 16° W 22.77' Set tag 41099

7" Maple Cluster N 48° W 48.70' Set tag 41099

Signed by *B-K. Fullford*

Surveyor's Michigan License No. 41099

Date 11/23/98

