

SURVEY & REMONUMENTATION

FEB 26 1998

SECTION

CHEBOYGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Cheboygan

(County)

Located In:

Corner Code #

1. Public Land Survey

T36NR 3W

1-3

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Brian K. Fullford, in a field survey on Nov. 6, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O.	1947 Norburt Sub.	1988 James Granger
1855 Harvey Mellen	Joseph Doyle	#16041
Reestablished corner	No Monument	1" Pipe
10" Hemlock N41°W	Identification Plat	P. Pole S49°E 48.18'
17 lks		14" Birch N22°W 54.48'
12" Hemlock S42°W		10" Maple S74°W 27.65'
37 lks		4" TW. Locust S25°W
		66.67

1993 Norm Quaine
#33984
1" Pipe @ West edge of
pavement
T. Pole S48°E 48.02'
10" Maple S74°W 27.75'
8" TW. Maple N32°W 43.40'
12" Birch N22°W 54.68'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe and 3 witnesses.

A. (Continued)

1905 David Bowen	1961 Dean DeLaMater
2 1/2" Square Cedar Post	3/4" Pipe atop 1" iron
1908 Survey David Bowen	P. Pole S11°E 103.5'
2" Square Cedar Post	P. Pole N18°E 148.5'
& G.L.O. wit	2" Cedar N81°E 36.3'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-3 Placed 5/8" rebar with remonumentation cap, and position is accepted as a careful and faithful perpetuation of the original corner.

P. Pole S 52° E 47.95'
4" Ash S 89° W 26.00'
8" Tw. Maple N 38° W 43.24'
15" Birch N 26° W 54.52'

W/Tag 15410
Set Tag 41099
W/Tag 15410
W/Tag 15410

LIBER 011 PAGE 06

Signed by

Surveyor's Michigan License No.

Date

