

# SURVEY & REMONUMENTATION

FEB 26 1998

## SECTION

## CHEBOYGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Cheboygan

(County)

Located in:

Corner Code #

1. Public Land Survey

T36NR 3W

T R

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

other  
#1

RECEIVED FOR RECORD 12-18-97  
at 10:57 O'Clock 4 M

*Joanne Spray*

CLERK/REGISTER  
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Brian K. Fullford, in a field survey on Sept. 17, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O.

1855 Harvey Mellen

Intersected Burt Lake at

old meander corner and

Reestablished same

12" W. Pine N 7° E 5 lks

6" Cedar S 29° E 6 lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Concrete monument recovered at witness corner to meander corner, deflection angle at Section corner to East checks good.

LIBER 011 PAGE 01

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-11 to K-11 Placed remonumentation cap on concrete monument, and position is accepted as a careful and faithful perpetuation of a witness corner to the original meander corner.

13" Triple Ash N 46° W 24.43'

Set Tag 41099

18" Twin Ash S 78° W 17.83'

Set Tag 41099

13" Ash S 1° W 34.66'

Set Tag 41099

Conc. Mon. North 7.19'

Set Tag 41099

60.13' to water's edge.

Signed by B. K. Fullford

Date 11/2/97

Surveyor's Michigan License No. 41099

