

SURVEY &
REMONUMENTATION

FEB 26 1998

CHEBOYGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Cheboygan

(County)

Located In:

Corner Code #

Other

1. Public Land Survey

T36N R 3W

#3

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

RECEIVED FOR RECORD 12-18-97
at 10:59 O'Clock A M

Joanne Spray

CLERK/REGISTRAR
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Brian K. Fullford, in a field survey on Sept. 16, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1995 James Granger #16041
1855 Harvey Mellen Found iron and survey ties to East
On old line of survey Liber 628, Page 493
14" Y. Pine S 56° E 20 lks
16" Y. Pine N 33° E 25 lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" pipe per Jim Granger Survey.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



LIBER 011 PAGE 03

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-9 to K-9 Placed 5/8" rebar with remonumentation cap inside pipe and is accepted as a careful and faithful perpetuation of the original corner.

S.W. corner of house N 43° E 40.16'
20" White Pine N 83° E 42.90'
8" Maple S 31° E 28.38'
13" Red Pine S 51° W 13.45'

Set Tag 41099
Set Tag 41099
Set Tag 41099

Water line 40' West

Signed by Brian K. Fullford
Surveyor's Michigan License No. 41099

Date 11/21/97

