

# SURVEY & REMONUMENTATION

FEB 26 1998

SECTION

## CHEBOYGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Cheboygan

(County)

Located In:

Corner Code #

Other

1. Public Land Survey

T 36NR 3W #4

T R

T R

T R

T R

T R

T R

T R

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

I, Brian K. Fullford, in a field survey on Nov. 6, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- |                                  |  |
|----------------------------------|--|
| G.L.O.                           | 1974 Richard Bidstrup  |
| 1855 Harvey Mellen               | #11360   |
| Reestablished old meander corner | Iron found and survey ties to corners to East, Liber 355, Page 395 |
| 10" Y. Pine on corner            |  |
| 6" Y. Pine S 36° E 4 lks         |  |

1979 Richard Bidstrup  
#11360  
Iron found and survey ties to East, Liber 401, Page 673

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Set witness corner to meander corner per G.L.O. deflection angle at Southeast Corner of Section 14..

LIBER 011 PAGE 04

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-7 to K-7 Placed 5/8" rebar with remonumentation cap and position is accepted as a careful and faithful reestablishment of a witness corner to the original meander corner. Corner is at the top of a bank 163.60' West of K-7.

18" Apple S 62° E 49.62'	Set Tag 41099
24" Cottonwood S 27° N 55.90'	Set Tag 41099
18" Cottonwood N 31° W 39.19'	Set Tag 41099
Wood fence post N 8° W 6.53'	Set Tag 41099

Signed by

Surveyor's Michigan License No.

41099

Date

11/21/97

RECEIVED FOR RECORD

at 11:00 O'Clock

12-18-97

A M

James Spray

CLERK/REGISTER

CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

