

1998

SECTION

1998
CHEBOYGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Cheboygan

Located In:

Corner Code #

RECEIVED FOR RECORD 1-8-99
at 9:10 O'Clock A M

Joanne Spray

CLERK/REGISTER
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

1. Public Land Survey

T^{36N} R^{3W}

9

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Brian K. Fullford

June

1998

do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1855 Harvey Mellon

GLO Resurvey

Set meander post

10" Balm of gilead N 66° E 4 lks

13.30 chains (877.8') West of

corner SE corner Sec. 3

Intersected Burts Lake

1947 Joseph Doyle

Set 4" X 48' Conc Mon

Plat of Norburt Sub.

No witnesses given

Distance from corner I-3 at

816.65'

1970 Doyle Civil Engineering

Unrecorded survey

Shows corner at 762.41 feet from
corner I-3 No witnesses given

1985 Richard Dunn

#12020 Unrecorded survey

No witnesses given

Distance from cor. I-3 given at
762.41 feet.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Find no evidence of any old or existing monument or accessory at position of corner as shown on surveys or plats, or on section line back from water's edge. Use Plat, unrecorded surveys, and monumentation in area as best evidence to place monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H3-I3 Placed 5/8" rebar with remonumentation cap, and position is accepted as a careful and faithful re-establishment of a witness corner to the original corner. Witness corner is 128 feet East of original Meander corner.

Placed witness corner at 755.00' West of Southeast Section corner.

5" Ash N 60° E 15.30'

Set Tag #41099

21" Ash S 69° E 44.57'

Set Tag #41099

15" Cedar S 31° E 23.27'

Set Tag #41099

10" Ash N 29° W 7.00'

Set Tag #41099

Waters edge 12' west

Signed by

Surveyor's Michigan License No.

41099

Date

11/23/98

