

1999 CHEBOYGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED
FOR RECORD

00 JAN -3 PM 12: 39

Shirley Pyzyrski
CLERK/REGISTER
CHEBOYGAN COUNTY MICHIGAN

MAR 03 2000

Register of Deeds Stamp & File Number

For corners in
Cheboygan

(County)

Located In:

Corner Code #

1. Public Land Survey

36N R 3W

13

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

Brian K. Fullford

October 1999

I, Brian K. Fullford, in a field survey on October 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Resurvey 1855

10" Willow on corner

18" Maple S78°W 58

Lks.

5.60 chains East of

1/4 cor.

Job #41-48 Doyle

Engineering

Pipe

No witnesses

given

May. 1950 O. Doyle

Rls. #7319

Fnd 1/4" pipe

No witnesses given

Nov. 1972

G.Young #10710

Fnd survey stake @

133.62' East of 1/2 cor.

No witness given

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fnd 3/4" pipe occupation line to West

Corner is 133.5' +/- East of 1/4 cor. as per Young survey of Nov. 1972 L 332, Pgs 004-006

9' West of edge of water no witness found

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D7-E7

Set 5/8" X 36" iron bar and remonumentation cap inside 3/4" pipe, and position is accepted as a careful and faithful re-establishment of a witness corner is 236 feet West of original corner.

Witness corner is 133.6 feet East of North 1/4 corner.

10" Tw Birch N1°E 35.02' Set tag 41099

4" Cedar S5°E 2.90' Set tag 41099

6" Ash West 14.97' Set tag 41099

12" Maple N15°W 24.68' Set tag 41099

Edge of water East 11.80'

Signed by

B. K. Fullford

Surveyor's Michigan License No.

41099

Date

12/17/99



LIBER 011 PAGE 181

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995