

RECEIVED
FOR RECORD

1999 CHEBOYGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

00 JAN -3 PM 12:40

For corners in
Cheboygan

(County)

Located In:

Corner Code #

1. Public Land Survey

36N R 3W

15

2. Property Controlling
in Section

S T

T R

3. Miscellaneous
Property in Sec.

S T

T R

CLERK/REGISTER
CHEBOYGAN COUNTY MICHIGAN

MAR 03 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Brian K. Fullford, in a field survey on Sept., 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Resurvey 1855
Find old meander corner
34.85 chains N89°54'E of corner E-9
10" Cedar on corner
12" Hemlock S5°W 17 Lks.

Oct. 1945 J. Doyle
Plat of Beauwood
Shows bearings of section line only

June 1954 T. Schweigert
Plat of Burt Lake Shores
Shows position of meander corner only

Doyle Civil Engineers
Survey drawing
Shows iron at meander corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Find 3/4" pipe w/smashed top

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E9-F9 Set 5/8" X 36" iron bar and remonumentation cap inside 3/4" pipe, and position is accepted as a careful and faithful re-establishment of the original corner.

Witness corner is 41 feet West of original corner.

Witness corner is 2258.8 feet East of Southwest Section corner

14" Cedar N7°E 16.68' w/tag 41099

6" Elm S84°E 16.74' w/tag 41099

13" Hemlock S38°W 16.38' w/tag 41099

22" Oak N63°W 29.13' w/tag 41099

Conc. Mon. S41°E 39.80'

Iron pipe N35°30'W 40.68'

Edge of water 18' East

Signed by

Date

Surveyor's Michigan License No. 41099

