

V/

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 37. NR. 1. E.

Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to sections 15, 16, 21, 22

DESCRIPTION OF CORNER MONUMENT 1" Iron pipe with 4" Brass cap

WITNESSES TO CORNER 5" F. Birch - N 74 E - 45 Links

4" Spruce - N 43 E - 44 Links


4" S. Maple - S 64 E - 7 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by Forestry Division Survey crew, while working
in this Township. Both original P.T.'s still in place, but in poor condition.
Definitely an original corner.

Corner was placed November 2, 1950.

SURVEYORS SEAL



SIGNED Sean C. DeLaMater DATE 12/14/50
REGISTERED LAND SURVEYOR