

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD


T. 37 N.R. 1 W.  
T. 38 N.R. 1 W.  
Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 1 - 2 - 35 - 36

CORNER MONUMENT Set 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED October 30, 1963

WITNESSES TO CORNER.....



12" R. Pine S 44 W 64.6'  
10" R. Pine N 84 E 38.3'  
AND  
8" R. Pine N 5 W 80.5'

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Found 3/4" pipe at corner as established in a previous survey by unknown surveyor. Unable to positively identify anything for U. S. BTs, but conforms fairly well with pattern of survey in this area. Considered acceptable as best evidence of corner.

SURVEYOR'S SEAL

SIGNED Kenneth Ostling DATE December 16, 1963  
REGISTERED LAND SURVEYOR