

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
CHEBOYGAN
(County)

Located In

Corner Code #

1. Public Land Survey	T	38N	R	02W	B-7
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	18	T	38N	R 02W
	S		T		R
					5

Register of Deeds Stamp & File Number

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on February 17, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-7 - 1/4 Corner common to sections 18 & 19, T38N, R02W

5 - CN 1/16 corner, section 18, T38N, R02W

1856 - GLO - Harvey Mellen- Set qr. Section post.
Hemlock 24 S03°E 24 links
Beech 9 N37°W 30 links

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

B-7 - 1/4 Corner common to sections 18 & 19, T38N, R02W

5 - CN 1/16 corner, section 18, T38N, R02W

Set standard DNR monument by proration to GLO along South line of section 18. Accepted location as a careful and faithful reestablishment of the position of the original corner. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-7 - 1/4 Corner common to sections 18 & 19, T38N, R02W

5 - CN 1/16 corner, section 18, T38N, R02W

4" dia. stamped alum. cap on 1"x 36" galvanized pipe.

2" dia. stamped aluminum cap on 5/8"x34" rebar.

Wit: N05°E 22.56' to set N&T on W side 8" R. Maple
S71°E 32.20' to set N&T on S side 11&13" Tw. R. Maple
S39°W 64.03' to set N&T on NW side 9" R. Maple
N15°W 58.58' to set N&T on SW side 9" R. Maple
Set Blue Carsonite Post 1' North

Wit: North 12.00' to set N&T on W side 5" B. Fir
S70°E 27.05' to set N&T on SW side 7" B. Fir
S51°W 11.00' to set N&T on S side 7" Twin B. Fir
N85°W 14.92' to set N&T on S side 10" B. Fir
Set Blue Carsonite Post w/ loc. tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

3-9-11

