

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 2 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 20 - 21 - 28 - 29

CORNER MONUMENT Left 3/4" iron bar in place

DATE MONUMENT PLACED AND WITNESSED April 17, 1963

WITNESSES TO CORNER.....



4" Twin Cedar S 44 W 53.4'

10" Spruce N 21 W 80.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this township. Found 3/4" iron bar at corner in line with roads N - S and E.

Best evidence of proper location for corner.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE April 24, 1963
REGISTERED LAND SURVEYOR
#10068