

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 38 N.R. 3 W.
T. 39 N.R. 3 W.


Cheboygan COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 34 - 35 - 2 - 3

CORNER MONUMENT Drove 1" pipe below surface

DATE MONUMENT PLACED AND WITNESSED April 22, 1964

WITNESSES TO CORNER.....



12" Balsam S 55 E 42.3'

7" Spruce S 54 W 40.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found 1/2" pipe in place in N - S road and in line with old grades E and W. Appears acceptable as proper location for corner.

SURVEYOR'S SEAL

SIGNED

Connelly Ostling
REGISTERED LAND SURVEYOR #10068

DATE

June 26, 1964