STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	<u>De</u>	elta	_COUNTY
	т	37 N R	24 W
DESCRIPTION OF CORNER	1/4 corner for sections 19/20		
CORNER MONUMENT	1" iron pipe with 4" aluminum cap		
DATE MONUMENT PLACED AND WITNESSED 6/13/69, F. J. Bray			
WITNESSES TO CORNER 6" Cedar (1/4 S) (NBT) S 70° W, 10 links			
2'0	10" Cedar (1/4 S) (NBT) N 35° W, 17	7½ links	
	AND		
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners to south and to north. Blazed stump and signature tree and wood post in vicinity. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

IGNED Frank Strang
REGISTERED LAND SURVEYOR

DATE 6/23/69

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing