

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Delta COUNTY
T 39 N R 18 W

DESCRIPTION OF CORNER 1/4 corner for Sections $\frac{2}{11}$

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 5/25/71 F. J. Bray

WITNESSES TO CORNER..... 6" Cedar (1/4 S) (NBT) N 71°E, 15.2'



10" Cedar (1/4 S) (NBT) S 47°W, 19.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from original B.T.'s, Tamarack to northwest has overgrowth of iron marks on upper face. Cedar to the southeast and rotted stump in proper bearing and distances. Corner found by survey crew.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

6/7/71

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68