

SURVEY &
REMONUMENTATION

SEP 18 1997

COMMISSION

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On July 23, 1992

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Walter C. Thorne
Acting Chairman

For corners in

DELTA

(County)

Located In:

Corner Code ##

28 July 1997

9:00 o'clock a.m.

8 Page 225

Walter C. Thorne
Delta County, Mich. Reg. of Deeds

Register of Deeds Stamp & File Number

1. Public Land Survey T 41 N R 23 W MC I-12/13 LT BANK
T R MC I-12/13 RT BANK
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, M.P. DAVIS, in a field survey on 16 JUNE, 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
I-12/13 [MC LT BANK] A. MERRYWEATHER, D.S.-1847-WOOD POST (ELM. 10"-N40°W-46 LINKS)
NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT CORNER RESTORATION.

- I-12/13 [MC RT BANK] JOHN BURT D.S.-1845-WOOD POST (BIRCH 14"-S42°W-47 LINKS)(CEDAR 12"-S55°E-29 LINKS)
NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT CORNER RESTORATION.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
I-12/13 [REF MON TO MC ON LT BANK] NO CORNER EVIDENCE FOUND. ESTABLISHED REFERENCE MONUMENT AT EDGE OF
UPLAND VEGETATION & ON THE LINE COMMON TO SEC'S 34/35

- I-12/13 [REF MON TO MC ON RT BANK] NO CORNER EVIDENCE FOUND. ESTABLISHED REFERENCE MONUMENT AT EDGE OF
UPLAND VEGETATION & ON THE LINE COMMON TO SEC'S 34/35

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-12/13 [LT BANK] SET A 5/8" X 18" REBAR W/A 3 1/4" ALUM CAP STAMPED TO ID THE CORNER POSITION.
MAPLE 9" ASPEN 10" W. BIRCH 12" SURVEY MONUMENT SIGN POST LT BANK ESCANABA RIVER
N46°W N05°W N30°E SOUTH SOUTH
32.81' 30.95' 53.02' 2.07' (TO FACE) 50'

I-12/13 [RT BANK] SET A 5/8" X 18" REBAR W/A 3 1/4" ALUM CAP STAMPED TO ID THE CORNER POSITION.
CEDAR 08" CEDAR 9" CEDAR 13" SURVEY MONUMENT SIGN POST RT BANK ESCANABA RIVER
S62°E S12°E S13°W N45°E NORTH
37.39' 21.28' 23.16' 1.94' (TO FACE) 25'

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT, UNLESS OTHERWISE NOTED.

Signed by M.P. Davis Date 7/23/97

Surveyor's Michigan License No. 16926

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

