

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 22W


Delta COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 5-8

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 7-7-61 with J. Bastian, Asst. D.F.

WITNESSES TO CORNER..... 8" Cedar (1/4 S NBT) N 23°E 33 links



8" Cedar (1/4 S NBT) South 40 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old cedar post. Found Cedar stumps bearing N59°E 28 links and S52°W 09 links for probable B.T.'s. No remaining marks on either stump.

Forest Service poster dated 1937 at Corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE January 31, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler