

RECORDED

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

1999 NOV 29 AM 10:31

For corners in

Dickinson

Located in:

Corner Code #

REGISTERED DEEDS
DICKINSON COUNTY
NOV 29 1999(County)
Waucedah Twp.

1. Public Land Survey

T 39NR 28W

E-10

G-10

2. Property Controlling
in Section

S

T

R

SURVEY 2

3. Miscellaneous
Property in Sec.

S

T

R

REMONUMENTATION

Register of Deeds Stamp & File Number

MAR 24 2000

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

SECTION

I, Robert F. Perkins, in a field survey on Oct. 12, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-10 $\frac{1}{4}$ Corner 29/28

Post by J.H. Mullett, D.S. 1849

Original Bearing Trees

Maple 3" N48°W 05 Lks.

Maple 3" S35°E 08 Lks.

G-10 $\frac{1}{4}$ Corner 28/27

Post by J.H. Mullett, D.S. 1849

N. Side Windfall

Original Bearing Trees

Birch 6" S11°E 10 Lks.

Elm 16" S87°E 15 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-10 No Evidence of Original Corner

or Accessories Found.

Found K.C. Corp. 1" Pipe Marker

with 4" Brass Cap as Established

by Neal Sperhake, RLS in 1963.

W.Pine N55°W 33 $\frac{1}{2}$ ' L. (Found)

Corner Report #760

G-10 No Evidence of Original Corner

or accessories found.

Corner Location established by

Single Proportionate Method between

Section Corner $\frac{1}{2}$ Mile North and $\frac{1}{2}$

Mile South.

ADMITTED BY THE DICKINSON COUNTY
SURVEYOR GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON
11-23-99

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-10 Accepted Marker described in B above.

New Witnesses

W.Pine 12" S77°E(M.B.) 4.19' Nail/Tag

W.Pine 16" N52°W(M.B.) 22.07' Nail/Tag

R.Pine 12" N5°E(M.B.) 47.38' Nail/Tag

R.Pine 18" S14°W(M.B.) 42.96' Nail/Tag

Placed Carsonite Marker 1.0' South

G-10 Set 2 $\frac{1}{2}$ " Stamped D.C. Remon. Marker

as described in "B" above.

New Witnesses

Maple 7" N27°W(M.B.) 26.24' Nail/Tag

Maple 12" N55°E(M.B.) 46.85' Nail/Tag

Maple 7" N69°W(M.B.) 31.76' Nail/Tag

Ash 4" S03°W(M.B.) 21.53' Nail/Tag

Signed by

Robert F. Perkins

Date

Nov. 5, 1999

Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

Libee 2

Page 1119