

DEC 18 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE NOV 22 PM 2:31
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey

K-7 14 13
23 24

L-7 13
24

T 39N R 29W
T 39N R 29W
T R
T R

K-7

L-7

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

REGISTER OF DEEDS
CLERK
JAN 1 1996

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, James H. Moore, in a field survey on September 6, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-7 Original Corner - Post Set by J. H. Mullet 1849
Original Bearing Trees
8" Y. Pine S28°E 30 Links
8" Aspen S60°W 12 Links

L-7 Original Corner - Post Set by J. H. Mullet 1849
Original Bearing Trees
15" Y. Pine N70°E 18 Links
18" W. Pine S20°W 39 Links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-7 Found 1½" Iron Pipe 2.3' Above Ground As Per Sundberg, Carlson's Notes
166' North of Hilltop, Located on N-S Fence Line, North Side of Treeline East
Record Research on File With Register of Deeds

L-7 Found Square Iron Bar As Per Sundberg, Carlson's Notes
8' North of Fence, 30' North of Centerline of Road on Centerline of Road Extended South
Record Research on File With Register of Deeds

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON

11-20-95
RJP

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-7 Replaced 1½" Iron Pipe With New Dickinson County Capped Aluminum Monument. Monument Stamped to Identify Corner. Referenced as Follows:
7" Maple S72°E 17.73'
8" Maple South 14.39'
11" Maple S61°W 7.61'
7" Maple N30°W 21.58'
Carsonite Rail NE 1.3'

L-7 Drove New Dickinson County Capped Aluminum Monument Along Side Square Iron Bar. Monument Stamped to Identify Corner. Referenced as Follows:
12" Jack Pine S77°E 26.09'
CL Telephone Riser S20°E 10.0'
SE Corner Electrical S65°W 8.0'
Pad S65°W 8.0'
7" Jack Pine N16°W 36.37'
Carsonite Rail North

Signed by James H. Moore
Surveyor's Michigan License No. 28423

Date 11/20/95

