

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T40N R27W
T40 NR 28 W

Dickinson and

Menominee

COUNTY

DESCRIPTION OF CORNER Section corner common to sections 13 and 24, T40N R28W
and sections 18 and 19, T40N R27W

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Cedar 11" N 53 W 28 1/2 links
marked S 13 NBT

Cedar 5" N 42 E 45 links
marked S 18 NBT

Cedar 9" S 25 W 28 links
marked S 24 NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was replaced from two original cedar bearing trees, one in good
condition, down with scribe marks plain, one in poor condition, stump in place
with no identifying marks.

Corner had been previously perpetuated by unknown surveyor. 2" iron pipe and
2 old wood posts in place.

Corner found while cruising timber in this area.

(1957)

Corner was placed and witnessed on 5 February with Clarence Ryberg.

SURVEYORS SEAL

Henry S. Peterson
SIGNED Henry S. Peterson
REGISTERED LAND SURVEYOR

DATE 2/10/57