

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 40 N. R. 29 W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 corner for section $\frac{7}{18}$

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/27/67, Frank J. Bray

WITNESSES TO CORNER..... 6" W. Pine (1/4S)(NBT) S 64° W, 76 Links



20" Hemlock (1/4S)(NBT) N 29° W, 90 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed on line and the single proportioned measurement between section corners to east and to west. No original evidence found.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 10/13/67
REGISTERED LAND SURVEYOR